


### "Other covering, loose" settlement joint – wall junction



\* Omission of surface waterproofing and wearing layer (see system description)

Drawing no.: BWS-2218